

---

# Contents

<b>List of Tables</b> .....	xxi
<b>Preface to This Edition</b> .....	xxvii
<b>Note from the Series Editor for the First Edition</b> .....	xxix
<b>Foreword to the First Edition</b> .....	xxxi
<b>Preface to the First Edition</b> .....	xxxiii
<b>Acknowledgments from the First Edition</b> .....	xxxv
<b>Authors</b> .....	xxxvii
<b>1 Introduction</b> .....	1
Acceptance Quality Control.....	1
Acceptance Control and Process Control.....	3
Process Quality Control.....	4
Background of Acceptance Quality Control.....	6
Top 10 Reasons for Acceptance Sampling.....	8
References.....	9
Problems.....	10
<b>2 Probability and the Operating Characteristic Curve</b> .....	11
Probability.....	11
Classical Definition.....	11
Empirical Definition.....	11
Subjective Definition.....	12
Random Samples and Random Numbers.....	12
Counting Possibilities.....	13
Probability Calculus.....	17
Operating Characteristic Curve.....	20
References.....	23
Problems.....	24
<b>3 Probability Functions</b> .....	25
Probability Distributions.....	26
Measures of Distribution Functions.....	28
Hypergeometric Distribution.....	31
Binomial Distribution.....	33
Poisson Distribution.....	36
f-Binomial Distribution.....	37
Negative Binomial Distribution.....	40
Exponential and Continuous Distributions.....	43
Weibull Distribution.....	44
Normal Distribution.....	46
Summary of Distributions.....	49

Tables of Distributions.....	49
Hypergeometric Tables .....	49
Binomial Tables .....	51
Poisson Tables .....	51
Negative Binomial Tables.....	52
Exponential and Weibull Tables.....	52
Normal Distribution Tables .....	53
Summary .....	53
Useful Approximations .....	54
Tests of Fit.....	57
References .....	60
Problems.....	61
<b>4 Concepts and Terminology .....</b>	<b>63</b>
Average Run Length of Type B Plans .....	66
Sample Size and Lot Size .....	66
Effect of Inspection Error .....	70
Rectification .....	71
Curtailment.....	74
Tolerance and Confidence Intervals .....	75
Levels and Risks .....	77
Choosing Quality Levels .....	79
Classification of Defects .....	80
Measures of Sampling Plans: Terminology.....	81
Graphs of Measures .....	83
Specifying a Plan .....	85
References .....	86
Problems.....	87
<b>5 Single Sampling by Attributes .....</b>	<b>89</b>
Operation.....	89
Selection.....	89
Tables of Poisson Unity Values .....	90
Binomial Nomograph.....	92
f-Binomial Nomograph.....	92
Thorndyke Chart .....	94
Hypergeometric Tables .....	95
Measures .....	97
References .....	99
Problems.....	100
<b>6 Double and Multiple Sampling by Attributes .....</b>	<b>103</b>
Operation.....	104
Double Sampling .....	104
Multiple Sampling .....	104
Selection.....	105
Measures .....	110
Double Sampling .....	110
Multiple Sampling .....	112
Further Considerations.....	120
References .....	121
Problems.....	121

<b>7</b>	<b>Sequential Sampling by Attributes</b> .....	123
	Operation.....	123
	Selection.....	125
	Measures.....	127
	Sequential Sampling for Defects per Unit.....	128
	References.....	129
	Problems.....	129
<b>8</b>	<b>Variables Sampling for Process Parameter</b> .....	131
	Single Sampling for Process Parameter.....	131
	Acceptance Control Charts.....	133
	Sequential Plans for Process Parameter ( $\sigma$ Known).....	136
	Sequential Plans for Process Parameter ( $\sigma$ Unknown).....	144
	Cumulative Sum Charts.....	146
	References.....	149
	Problems.....	150
<b>9</b>	<b>Bulk Sampling</b> .....	153
	Construction of the Sample.....	154
	Estimation.....	156
	Sampling Plans.....	164
	Simple Random Sampling of a Unique Lot (Components of Variance Unknown).....	166
	Sampling from Stream of Lots.....	168
	Estimation of Testing and Reduction Variances.....	169
	Estimation of Segment and Increment Variances.....	169
	Application of Plan to Stream of Lots.....	170
	References.....	173
	Problems.....	174
<b>10</b>	<b>Sampling by Variables for Proportion Nonconforming</b> .....	175
	Specification Limits.....	176
	Assumptions and Theory.....	177
	Operation.....	179
	$\bar{X}$ Method.....	179
	$k$ Method.....	179
	Double Specification Limits.....	180
	Selection.....	184
	Tables.....	184
	Formulas.....	185
	Jacobson Nomograph for Plan Selection.....	186
	Measures.....	188
	Jacobson Nomograph for Operating Characteristics.....	188
	Calculation: $\sigma$ Known.....	189
	Calculation: $\sigma$ Unknown.....	191
	Double Specification Limits.....	194
	Measures of Performance.....	194
	$M$ Method.....	197
	Plans Based on Sample Range.....	201
	Double Sampling by Variables.....	205
	Tolerance Intervals and Variables Plans for Percent Nonconforming.....	207
	Sequential Plans for Proportion Nonconforming.....	211

	Further Considerations .....	212
	Derivation of $n$ , $k$ Formulas .....	212
	Need for Normality .....	214
	References .....	214
	Problems .....	215
<b>11</b>	<b>Attributes Sampling Schemes .....</b>	<b>217</b>
	Sampling Schemes .....	217
	Quick Switching Systems .....	217
	TNT Plans .....	219
	MIL-STD-105E and Derivative Standards .....	219
	Operation .....	221
	Selection .....	223
	Measures .....	226
	Scheme Properties .....	227
	Implementation of MIL-STD-105E .....	228
	Matching Individual Sampling Plans to MIL-STD-105E System Performance .....	232
	MIL-STD-105 Derivatives .....	235
	Further Considerations .....	237
	References .....	238
	Problems .....	239
<b>12</b>	<b>Variables Sampling Schemes .....</b>	<b>241</b>
	MIL-STD-414 .....	241
	Operation .....	243
	Selection .....	245
	Measures .....	247
	Implementation of Form 2 .....	248
	Implementation of Form 1 .....	250
	Implementation of Plans for Range and Variability Known .....	251
	Match between MIL-STD-414 and MIL-STD-105E .....	252
	Conversion of MIL-STD-414 to ANSI/ASQ Z1.9 .....	253
	MIL-STD-414 Derivatives .....	253
	ANSI/ASQ Z1.9 .....	253
	ISO 3951-1 .....	254
	Further Considerations .....	256
	References .....	256
	Problems .....	257
<b>13</b>	<b>Special Plans and Procedures .....</b>	<b>259</b>
	No-Calc Plans .....	259
	Lot Plot Plans .....	261
	Narrow-Limit Gauging .....	265
	Mixed Variables—Attributes Plan .....	275
	Advantages and Disadvantages of Mixed Plans .....	277
	Generalized Mixed Dependent Procedure .....	278
	Measures: Independent Mixed Plan .....	279
	Measures: Dependent Mixed Plan .....	281
	MIL-STD-414 Dependent Mixed Plans .....	285
	Comparison of Independent and Dependent Mixed Plans .....	287
	Comparison of Mixed with Other Type Plans .....	287

References .....	289
Problems .....	290
<b>14 Series of Lots: Rectification Schemes .....</b>	<b>293</b>
Single-Sampling AOQL Plan .....	294
Dodge–Romig Sampling Scheme .....	294
Operation .....	296
Selection .....	296
Measures .....	303
Further Considerations .....	303
Constructing LTPD Plan with Minimum ATI .....	308
Constructing AOQL Plan with Minimum ATI .....	310
Anscombe Rectifying Inspection Procedure .....	313
Operation .....	313
Selection .....	313
Measures .....	316
Credit-Based Schemes .....	317
References .....	319
Problems .....	319
<b>15 Continuous Sampling Plans .....</b>	<b>321</b>
Dodge Continuous Plans .....	321
Dodge CSP-1 .....	321
Dodge–Torrey CSP-2 and CSP-3 .....	323
Measures of CSP-1, 2, and 3 .....	327
Stopping Rules and Selection of CSP-1 Plans .....	331
Multilevel Plans .....	334
Tightened Multilevel Plans .....	337
Block Continuous Plans .....	338
Wald–Wolfowitz Plan .....	338
Girshick Plan .....	340
MIL-STD-1235B .....	341
References .....	348
Problems .....	349
<b>16 Cumulative Results Plans .....</b>	<b>351</b>
Skip-Lot Sampling Plans .....	351
SkSP-1 .....	351
SkSP-2 .....	353
Chain Sampling Plans .....	358
ChSP-1 .....	358
Two-Stage Plans .....	362
Deferred Sentencing Schemes .....	363
Demerit Rating Plan .....	366
CRC Plan .....	370
References .....	373
Problems .....	374
<b>17 Compliance Sampling .....</b>	<b>375</b>
LSP .....	376
Procedure .....	376
Protection .....	377

Producer's Risk .....	378
Examples of LSP Applications .....	379
Further Considerations .....	380
TNT Scheme .....	381
Procedure .....	381
Protection .....	382
Selection .....	383
Quick Switching System (QSS).....	385
MIL-STD-1916 .....	386
Structure .....	386
Operation .....	387
Implementation .....	389
Measures .....	391
Further Considerations .....	391
Simplified Grand Lot Procedure .....	391
Simon's Approach.....	392
Simplified Procedure: Attributes.....	394
Example: Attributes .....	395
Simplified Procedure: Variables .....	396
Continuing Series of Lots .....	402
Further Considerations .....	405
Nomograph for Samples Having Zero Defectives .....	406
Accept on Zero (AOZ) Plans.....	407
U.S. Department of Defense Approach .....	407
Squeglia Plans .....	408
AOZ and AQL Plans .....	410
Chain Sampling Alternative.....	411
Summary .....	413
References .....	413
Problems.....	414
<b>18 Reliability Sampling.....</b>	<b>417</b>
Censored Sampling .....	418
Variables Plans for Life Testing and Reliability .....	420
Handbook H-108.....	420
Operation.....	422
Failure Terminated .....	422
Time Terminated.....	424
Sequential .....	424
Proportion Failing by Specified Time .....	424
Selection .....	424
Example of H-108 Application.....	427
Failure Terminated .....	427
Time Terminated.....	427
Sequential .....	427
Proportion of Lot Failing by Specified Time .....	429
Measures .....	430
Further Considerations .....	430
Technical Report TR7.....	430
Mean Life Criterion .....	432
Hazard Rate Criterion .....	433

Reliable Life Criterion .....	434
TR7 Tables .....	434
Operation .....	436
TR7 with the MIL-STD-105E System .....	440
Further Considerations .....	441
References .....	444
Problems .....	445
<b>19 Administration of Acceptance Sampling .....</b>	<b>447</b>
Selection and Implementation of a Sampling Procedure .....	449
Determining Quality Levels .....	452
Setting AQL .....	453
Setting AOQL .....	456
Setting IQ .....	456
Setting LTPD (or LQ) .....	456
Relation of Levels .....	457
Setting PQL and CQL .....	457
Economic Considerations .....	459
Mandatory Standards .....	461
Computer Programs .....	461
Basic Principle of Administration .....	461
References .....	462
Problems .....	463
<b>Appendix .....</b>	<b>465</b>
<b>Answers to Problems .....</b>	<b>653</b>
<b>Author Index .....</b>	<b>671</b>
<b>Subject Index .....</b>	<b>675</b>